



03560.002666 (35.G2666)

COFC/16
PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:)
YASUO SUDA) Examiner: Kelly L. Jerabek
Appln. No.: 09/698,241) Group Art Unit: 2612
Filed: October 30, 2000) Patent No.: 6,933,978 B1
For: FOCUS DETECTING DEVICE WITH)
PHOTOELECTRIC CONVERSION : November 22, 2005
PORTION HAVING MICROLENS AND)
WITH LIGHT BLOCKING PORTION :
HAVING FIRST AND SECOND OPENINGS)
Issued: August 23, 2005

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

*Certificate
NOV 28 2005
Of Correction*

Attention: CERTIFICATE OF CORRECTION BRANCH

REQUEST FOR CERTIFICATE OF CORRECTION
UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form (Form PTO-1050), in duplicate, is enclosed.

11/25/2005 WABDELR1 00000064 6933978

01 FC:1811

100.00 OP

NOV 29 2005

Accompanying this letter is a check for \$100.00 to cover the statutory fee for issuing a Certificate of Correction to correct errors of the patentee. Any deficiency should be charged, or any overpayment credited, to Deposit Account No. 06-1205. A duplicate of this paper is enclosed for this purpose.

Patentee's undersigned attorney may be reached by telephone in our Washington, D.C. office at (202) 530-1010 or by facsimile at (202) 530-1055. All correspondence should be directed to our address given below.

Respectfully submitted,



Daniel S. Glueck
Daniel S. Glueck
Attorney for Patentee
Registration No. 37,838

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
Facsimile: (212) 218-2200

DSG/lw

DC_MAIN 220258v1

Staple
Here
Only

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 6,933,978 B1

DATED : August 23, 2005

INVENTOR(S) : Yasuo Suda

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

ON THE TITLE PAGE

Item (57), Abstract, line 3, "a image" should read --an image--.

COLUMN 6

Line 45, "MOSS" should read --MOS--.

Line 49, "an photoelectric" should read --a photoelectric--.

Line 64, "an vertically" should read --a vertically--.

COLUMN 9

Line 10, "With" should read --with--.

COLUMN 10

Line 18, "conversion G2" should read --conversion section G2--.

Line 25, "optical axis" should read --optical axis L1--.

COLUMN 13

Line 21, "increase" should read --increases--.

COLUMN 15

Line 3, "φPGoo" (second occurrence) should read --φPGeo--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,933,978 B1

No. of add'l. copies
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)

(Form#30) DSG/lp DC_MAIN 220260

NOV 29 2005

Staple
Here
Only!

PRINTERS TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 6,933,978 B1

DATED : August 23, 2005

INVENTOR(S) : Yasuo Suda

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 17

Line 22, "pulse ϕT_N ," should read --pulse ϕT_N --.

COLUMN 18

Line 9, "pixels" should read --pixel--.

COLUMN 20

Line 10, "an phase" should read --a phase--.

COLUMN 24

Line 55, "an light" should read --a light--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,933,978 B1

No. of add'l. copies
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)

(Form#30) DSG/lip DC_MAIN 220260

NOV 29 2005

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,933,978 B1

DATED : August 23, 2005

INVENTOR(S) : Yasuo Suda

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

ON THE TITLE PAGE

Item (57), Abstract, line 3, "a image" should read --an image--.

COLUMN 6

Line 45, "MOSS" should read --MOS--.

Line 49, "an photoelectric" should read --a photoelectric--.

Line 64, "an vertically" should read --a vertically--.

COLUMN 9

Line 10, "With" should read --with--.

COLUMN 10

Line 18, "conversion G2" should read --conversion section G2--.

Line 25, "optical axis" should read --optical axis L1--.

COLUMN 13

Line 21, "increase" should read --increases--.

COLUMN 15

Line 3, "φPGoo" (second occurrence) should read --φPGeo--.

MAILING ADDRESS OF SENDER:

PATENT NO. 6,933,978 B1

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

No. of add'l. copies
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)

(Form#30) DSG/lp DC_MAIN 220260



NOV 29 2005

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,933,978 B1

DATED : August 23, 2005

INVENTOR(S) : Yasuo Suda

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 17

Line 22, "pulse ϕT_N ," should read --pulse ϕT_N --.

COLUMN 18

Line 9, "pixels" should read --pixel--.

COLUMN 20

Line 10, "an phase" should read --a phase--.

COLUMN 24

Line 55, "an light" should read --a light--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,933,978 B1No. of add'l. copies
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)

(Form #30) DSG/lp DC_MAIN 220260

NOV 29 2005